



STATE OF ARKANSAS
Department of Pollution Control and Ecology
P. O. Box 8913 Little Rock, Arkansas 72219-8913
Telephone 501-562-7444

1 94

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039. Expires 9-30-

UNIFORM HAZARDOUS
WASTE MANIFEST

1. Generator's US EPA ID No.

Manifest
Document No.

2. Page 1

Information in the shaded areas is not
required by Federal law.

C A D 0 8 6 5 1 0 0 0 5 1 7 2 0 4 8

of 2

3. Generator's Name and Mailing Address

Douglas Aircraft Co. Attn. R. Tue11 M/S C6-59
19503 S. Normandie Ave. Torrance, CA 90502

A. State Manifest Document Number

AR-572048

B. State Generator's ID

HATQ3605698

4. Generator's Phone (310) 533-7926 or 310-533-7231

5. Transporter 1 Company Name

United Pumping Services

6. US EPA ID Number

C A D 0 7 2 9 5 3 7 7 1

C. State Transporter's ID

PC 1123 602

D. Transporter's Phone 213-268-3137

7. Transporter 2 Company Name

8. US EPA ID Number

E. State Transporter's ID

PC - - - - H - - -

F. Transporter's Phone

9. Designated Facility Name and Site Address

Ensco Inc.
American Oil Rd.
El Dorado, AR 71730

10. US EPA ID Number

I A R D 0 6 9 7 4 8 1 9 2

G. State Facility's ID

H. Facility's Phone

501-863-7173

11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)

12. Containers

No.

Type

13. Total
Quantity

14. Unit
Wt/Vol

1. Waste No.

a. Non-RCRA Hazardous Waste Solid
(lab-pack)

001

D M

01011010

P

551

N/R

b. Non-RCRA Hazardous Waste Liquid
(lab-pack)

001

D I F

0101080

P

551

N/R

c. ~~Waste Oxidizer, nos~~ (lab-pack)
~~Oxidizer, UN1479~~ JC

JC

JC

551

D001

d. Waste Sodium Nitrate (lab-pack)
Oxidizer, UN1498

0101

D I F

01010115

P

551

D001

J. Additional Descriptions for Materials Listed Above

a)drum# DT-001

c)drum# DT-003 JC

all drums

b)drum# DT-002

d)drum# DT-004

Profile# 200565

K. Handling Codes for Wastes Listed Above

EMERGENCY RESPONSE INFORMATION:

310-533-7926 Rob Tue11

if no alternate TSDF, return to generator

Revd 529#

15. Special Handling Instructions and Additional Information

In case of emergency contact Chemtrec at 800-424-9300. Weights are approximate.
DOT ERG# a)N/A b)N/A c)35 d)35

Load # 74280. Appx time 1000 on 1/8/92.

16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and Arkansas state regulations.

If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.

Printed/Typed Name

JOHN CHAN

Signature

John Chan

Month Day Year

10/10/593

17. Transporter 1 Acknowledgement of Receipt of Materials

Printed/Typed Name

Robert Hayes

Signature

Robert Hayes

Month Day Year

01/05/93

18. Transporter 2 Acknowledgement of Receipt of Materials

Printed/Typed Name

Signature

Month Day Year

19. Discrepancy Indication Space

20. Facility Owner or Operator Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.

Printed/Typed Name

Kenese Smith

Signature

Kenese Smith

Month Day Year

01/05/93

EPA Form 8700-22 (Rev. 9-88) Previous edition is obsolete.

NOTICE: THE ORIGINAL AND NOT LESS THAN TWO (2) COPIES MUST MOVE WITH THE HAZARDOUS WASTE SHIPMENT. ONCE DELIVERED, THE TREATMENT/STORAGE/DISPOSAL FACILITY MUST RETURN THIS ORIGINAL COPY TO THE GENERATOR.

BOE-C6-0194134

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator's US EPA ID No.		Manifest Document No.		22. Page		Information in the shaded areas is not required by Federal law.					
		CAD086510005		72048		2 of 2							
23. Generator's Name Douglas Aircraft Company						L. State Manifest Document Number AR-572048							
						M. State Generator's ID HAH036005698							
24. Transporter <u>1</u> Company Name		25. US EPA ID Number		N. State Transporter's ID		PC1123 H602							
United Pumping Services		CAD072953771		O. Transporter's Phone		213-268-3137							
26. Transporter _____ Company Name		27. US EPA ID Number		P. State Transporter's ID									
				Q. Transporter's Phone									
28. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)						29. Containers		30. Total		31. Unit		R. Waste No.	
						No. Type		Quantity		Wt/Vol			
a. <div style="border: 1px solid black; padding: 2px;">Waste Barium Nitrate (lab-pack) Oxidizer, UN1446</div>						001 D F		0025 P				551 D001	
b. <div style="border: 1px solid black; padding: 2px;">Waste Flammable Liquid, nos (lab-pack) Flammable Liquid, UN1993</div>						001 D F		0.030 P				551 D001	
c. <div style="border: 1px solid black; padding: 2px;">Waste Poison B Liquid, nos (lab-pack) Poison B, UN2810</div>						001 D F		0.040 P				551 P106, D005 D007, D006	
d. <div style="border: 1px solid black; padding: 2px;">Waste Titanium metal powder, dry (lab-pack) Flammable Solid, UN2546</div>						001 D F		0.045 P				551 D001	
e. <div style="border: 1px solid black; padding: 2px;">Waste Organic Peroxide Liquid, nos (lab-pack) Organic Peroxide, NA9183</div>						001 D F		0.015 P				551 D001	
f. <div style="border: 1px solid black; padding: 2px;">Waste Poison B solid, nos (lab-pack) PoisonB, UN2811</div>						001 D F		0.025 P				551 D006	
g. <div style="border: 1px solid black; padding: 2px;">Waste Corrosive Liquid, nos (lab-pack) Corrosive Material, UN1760</div>						002 D F		0.0180 P				551 D002	
h. <div style="border: 1px solid black; padding: 2px;"></div>													
i. <div style="border: 1px solid black; padding: 2px;"></div>													
S. Additional Descriptions for Materials Listed Above a)drum# DT-005 e)drum# DT-009 all drums b)drum# DT-006 f)drum# DT-010 Profile# 200565 c)drum# DT-007 g)drum# DT-012,011 d)drum# DT-008						T. Handling Codes for Wastes Listed Above							
32. Special Handling Instructions and Additional Information In case of an emergency contact Chemtrec at 800-424-9300. Weights are approximate. DOT# a)42 b)27 c)55 d)37 e)52 f)53 g)60													
33. Transporter <u>1</u> Acknowledgement of Receipt of Materials										Date			
Printed/Typed Name <i>Robert Hayes</i>						Signature <i>R Hayes</i>				Month Day Year 01 10 93			
34. Transporter _____ Acknowledgement of Receipt of Materials										Date			
Printed/Typed Name						Signature				Month Day Year			
35. Discrepancy Indication Space													

501-863-7173



American Oil Road
P.O. Box 1957
El Dorado, Arkansas 71731

DATE: 01-08-93

Douglas Aircraft Co.
19503 S. Normandie Ave
Lorrance, Ca. 90502
Attn: R. Well MS C6-59

Re: Arkansas Manifest # 572048

Dear Sir/Madame:

This letter is to notify you of an estimated weight discrepancy on the above referenced Arkansas manifest. The manifested estimate weight was RCPA 375 LBS.. The actual weight as received by ENSCO's Receiving Department was RCPA 300 LBS.

Please retain this notification for your files. No further action on your part is necessary. If you have any questions, please feel free to call me at (501) 864-3608.

Sincerely,


Deleza E. Johnson
Data Center Manager

cc: File

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)	21. Generator's US EPA ID No. CAD086510005	Manifest Document No.	22. Page 2 of 2	Information in the shaded areas is not required by Federal law.		
	23. Generator's Name Douglas Aircraft Company		L. State Manifest Document Number AR-572048			
24. Transporter 1 Company Name United Pumping Services		25. US EPA ID Number CAD072953771		M. State Generator's ID HAH036005698		
26. Transporter Company Name		27. US EPA ID Number		N. State Transporter's ID PC1123 H602		
				O. Transporter's Phone 213-268-3137		
				P. State Transporter's ID		
				Q. Transporter's Phone		
28. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		29. Containers No.	Type	30. Total Quantity	31. Unit Wt/Vol	R. Waste No.
a.	Waste Barium Nitrate (lab-pack) Oxidizer, UN1446		D F			551 D001
b.	Waste Flammable Liquid, nos (lab-pack) Flammable Liquid, UN1993		D F			551 D001
c.	Waste Poison B Liquid, nos (lab-pack) Poison B, UN2810		D F			551 P106, D005 D007, D006
d.	Waste Titanium metal powder, dry (lab-pack) Flammable Solid, UN2546		D F			551 D001
e.	Waste Organic Peroxide Liquid, nos (lab-pack) Organic Peroxide, NA9183		D F			551 D001
f.	Waste Poison B solid, nos (lab-pack) Poison B, UN2811		D F			551 D006
g.	Waste Corrosive Liquid, nos (lab-pack) Corrosive Material, UN1760		D F			551 D002
h.						
i.						
S. Additional Descriptions for Materials Listed Above a)drum# DT-005 e)drum# DT-009 all drums b)drum# DT-006 f)drum# DT-010 Profile# 200565 c)drum# DT-007 g)drum# DT-012,011 d)drum# DT-008			T. Handling Codes for Wastes Listed Above			
32. Special Handling Instructions and Additional Information In case of an emergency contact Chemtrec at 800-424-9300. Weights are approximate. DOT# a)42 b)27 c)55 d)37 e)52 f)53 g)60						
TRANSPORTER	33. Transporter Acknowledgement of Receipt of Materials			Date		
	Printed/Typed Name		Signature	Month Day Year		
FACILITY	34. Transporter Acknowledgement of Receipt of Materials			Date		
	Printed/Typed Name		Signature	Month Day Year		
35. Discrepancy Indication Space						



STATE OF ARKANSAS
Department of Pollution Control and Ecology
P. O. Box 8913 Little Rock, Arkansas 72219-8913
Telephone 501-562-7444

6

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039. Expires 9-30-92

AR-5-92

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.	Manifest Document No.	2. Page 1 of	Information in the shaded areas is not required by Federal law.
3. Generator's Name and Mailing Address Douglas Aircraft Co. Attn. R. Tuel M/S C6-59 19503 S. Normandie Ave. Torrance, CA 90502		C A D 0 8 6 5 1 0 0 0 5 1 7 2 0 4 8 R03 03-24-23		A. State Manifest Document Number AR-572048	
4. Generator's Phone (310) 533-7926 or 310-533-7231		5. Transporter 1 Company Name United Pumping Services		B. State Generator's ID	
6. US EPA ID Number C A D 0 7 2 9 5 3 7 7 1		7. Transporter 2 Company Name		C. State Transporter's ID PC 1123 H02-	
8. US EPA ID Number		9. Designated Facility Name and Site Address Ensco Inc. American Oil Rd. El Dorado, AR 71730		D. Transporter's Phone 213-268-3137	
10. US EPA ID Number		11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		E. State Transporter's ID PC - - - H - - -	
12. Containers		13. Total Quantity		14. Unit Wt/Vol	
No. Type		I. Waste No.			
a. Non-RCRA Hazardous Waste Solid (lab-pack)		551			
b. Non-RCRA Hazardous Waste Liquid (lab-pack)		N/R			
c. Waste Oxidizer, nos (lab-pack) Oxidizer, UN1479		551			
d. Waste Sodium Nitrate (lab-pack) Oxidizer, UN1498		N/R			
J. Additional Descriptions for Materials Listed Above		K. Handling Codes for Wastes Listed Above			
a)drum# DT-001 c)drum# DT-003 all drums b)drum# DT-002 d)drum# DT-004 Profile# 200565		EMERGENCY RESPONSE INFORMATION: 310-533-7926 Rob Tuel			
If no alternate TSDF, return to generator					
15. Special Handling Instructions and Additional Information In case of emergency contact Chemtrec at 800-424-9300. Weights are approximate. DOT ERG# a)N/A b)N/A c)35 d)35					
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.					
Printed/Typed Name John C. Tuel		Signature [Signature]		Month Day Year 10/1/92	
17. Transporter 1 Acknowledgement of Receipt of Materials					
Printed/Typed Name Robert H. Hume		Signature [Signature]		Month Day Year 10/1/92	
18. Transporter 2 Acknowledgement of Receipt of Materials					
Printed/Typed Name		Signature		Month Day Year	
19. Discrepancy Indication Space					
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.					
Printed/Typed Name		Signature		Month Day Year	

GENERAL INFORMATION

The Hazardous Waste manifest is designed to track waste from the point of generation to final disposal (cradle to grave). In order to accomplish this goal, it is essential that all items on the manifest be completed correctly. Incomplete or incorrect manifests are violations of the law, and could make you subject to civil or criminal liabilities as specified in the Federal Regulations and the Arkansas Hazardous Waste Management Code.

INSTRUCTIONS—IMPORTANT: READ ALL INSTRUCTIONS BEFORE COMPLETING

State and Federal regulations require Generators, Transporters, and Treatment, Storage & Disposal Facilities (TSDFs) to use this form and if necessary the continuation sheet for both inter and intrastate shipments. (Continuation sheets are not provided by the state of Arkansas.)

The Arkansas Manifest contains 6 copies. **ALL COPIES MUST BE LEGIBLE.** This form is designed for use on a 12 pitch (elite) typewriter; a firm ball point pen may also be used only if you press down **HARD**. The 6 copies must be distributed in the following way:

- ORIGINAL: **GENERATOR COPY**—The TSDF will mail back to the generator state where the waste was generated. (WHITE COPY)
- COPY 2: **STATE COPY**—The in-state TSDF mails to Arkansas Department of Pollution Control. (YELLOW COPY)
- COPY 3: **TSDF COPY**—TSDF keeps this copy for his records. (PINK COPY)
- COPY 4: **2ND TRANSPORTER COPY**—The second transporter keeps for his records. (GOLD COPY)
- COPY 5: **1ST TRANSPORTER COPY**—The first transporter keeps for his records. (GREEN COPY)
- COPY 6: **GENERATOR INITIAL COPY**—The generator keeps once first transporter signs off and takes waste. (BLUE COPY)

IF THE TSDF IS LOCATED OUT-OF-STATE THE IN-STATE GENERATOR MUST SEND A PHOTOCOPY TO THE ARKANSAS DEPARTMENT OF POLLUTION CONTROL ONCE THE MANIFEST HAS BEEN SIGNED OFF BY THE TSDF.

MANIFEST FORM ACQUISITION

1. If the destination (consignment) state supplies a manifest and requires its use, then the generator is obligated to obtain the manifest from that state.
2. If the destination state does not supply the manifest, but the generator state does, then the generator is obligated to obtain the manifest form from the generator state.
3. If forms are unavailable from either state the generator may obtain a manifest from any source.

ARKANSAS WILL NOT ACCEPT THE GENERIC UNIFORM MANIFEST

GENERATOR SECTION

- Item 1: **GENERATOR'S US EPA ID NO.—MANIFEST DOCUMENT NO.**—Enter the generator's 12 digit EPA identification number. The manifest document number is a unique 5-digit no. the generator assigns to each manifest.
- Item 2: **PAGE 1 Of**—Enter the total number of pages used to complete this manifest; i.e., the first page plus the number of continuation sheets, if any.
- Item 3: **GENERATOR'S NAME & MAILING ADDRESS**—Enter the name and mailing address of the generator, and provide the site address.
- Item 4: **GENERATOR'S PHONE NUMBER**—Enter a telephone no. with area code where an authorized agent of the generator can be reached in case of an emergency.
- Item 5: **TRANSPORTER 1 COMPANY NAME**—Enter the company name (as notified to EPA) of the first transporter who will transport the waste.
- Item 6: **US EPA ID NUMBER**—Enter the US EPA 12-digit ID number of the first transporter identified in Item 5.
- Item 7: **TRANSPORTER 2 COMPANY NAME**—If applicable, enter the company name (as notified to EPA) of the second transporter who will transport the waste. If more than (2) transporters will be used, use a continuation sheet and list the transporters in the order they will be transporting the waste.
- Item 8: **US EPA ID NUMBER**—If applicable, enter the US EPA 12-digit ID number of the second transporter identified in Item 7.
- Item 9: **DESIGNATED FACILITY NAME & SITE ADDRESS**—Enter the company name and site address of the treatment, storage, disposal facility (TSDF) designated to receive the waste listed on this manifest.
- Item 10: **US EPA ID NUMBER**—Enter the 12-digit US EPA identification number of the designated TSDF listed in Item 9.
- Item 11: **US DOT DESCRIPTION**—All of the following must be entered: the correct US DOT (Dept. of Transportation) name for the waste identified, the assigned DOT Hazard Class and the UN/NA ID Number (e.g. waste sulfuric acid, spent corrosive material, UN1832 RQ). The word "waste" must appear as part of the DOT name. If more than 4 wastes are being shipped, a second manifest or continuation sheets must be used. (See 49 CFR 172.201).
- Item 12: **CONTAINERS (NO. & TYPE)**—Enter the number of containers for each waste and the appropriate abbreviations from Table 1 (below) for the type of containers used:

TABLE 1
CONTAINER TYPES

DM	- Metal drums, barrels, kegs
DW	- Wooden drums, barrels, kegs
DF	- Fiberboard or plastic drums, barrels, kegs
TP	- Tanks portable
TT	- Cargo tanks (tank trucks)
TC	- Tank cars
DT	- Dump truck
CY	- Cylinders
CM	- Metal boxes, cartons, cases (including roll-offs)
CW	- Wooden boxes, cartons, cases
CF	- Fiber or plastic boxes, cartons, cases
BA	- Burlap, cloth, paper or plastic bags

- Item 13: **TOTAL QUANTITY**—Enter the total quantity of waste described on each line.

DO NOT USE FRACTIONS

- Item 14: **UNIT (Wt./Vol.)**—Enter the appropriate abbreviation from Table 2 (below) for the unit of measure used in determining the total quantity of waste described on each line.

TABLE 2
UNITS OF MEASURE

G	- Gallons (liquid only)
P	- Pounds
T	- Tons (2,000 lbs.)
Y	- Cubic yards
L	- Liters (liquids only)
K	- Kilograms
M	- Metric Tons (1,000 kg)
N	- Cubic meters

- Item 15: **SPECIAL HANDLING INSTRUCTIONS & ADDITIONAL INFORMATION**—Use this space to indicate special transportation, treatment, storage, disposal, or Bill of Lading information. If any alternate facility is designated, note it here. For **INTERNATIONAL SHIPMENTS**, generators must enter the point of departure (city & state) in this space.

- Item 16: **GENERATOR'S CERTIFICATION**—The Generator must read, sign (by hand), and date the certification. If a mode other than highway is used, the word "highway" should be lined out and the appropriate mode (rail, water, air) inserted in the space. If another mode in addition to the highway mode is used, enter the appropriate additional mode in the space.

- Item A: **STATE MANIFEST DOCUMENT NUMBER**—Number preprinted by the state of Arkansas except on the continuation sheets. Enter this number on each continuation sheet attached to the manifest.

- Item B: **STATE GENERATOR ID**—Are numbers issued by state of Arkansas (i.e., PCB, Provisional, or Conditionally Exempt Generator Numbers).

- Item C: **STATE TRAN #1 ID**—Must have Arkansas Permit Number if transporting waste in, through, or out of Arkansas.

- Item D: **TRANSPORTER PHONE**—Enter a telephone number with area code where an authorized agent of the transporter can be reached.

- Item E: **STATE TRAN #2 ID**—If applicable, enter Arkansas Permit Number if carrying waste in, through, or out of the Arkansas.

- Item F: **TRANSPORTER PHONE**—If applicable, enter a telephone number with area code where an authorized agent of the second transporter may be reached.

- Item G: **STATE FACILITY'S ID**—No entry is required by Arkansas.

- Item H: **FACILITY PHONE**—Enter a telephone number with area code of the TSDF designated to receive the waste listed on the manifest.

- Item I: **WASTE NO.**—Enter the 4-digit EPA Hazardous Waste No. as listed in 40 Code of Federal Regulations Part 261.

- Item J: **ADDITIONAL DESCRIPTIONS FOR MATERIALS LISTED BELOW**—List additional description of material and alternate TSDF including TSDF address and EPA ID Number.

- Item K: **EMERGENCY RESPONSE INFORMATION**—Arkansas requires the generator to list an authorized representative name and 24 hour phone number in case of an emergency.

TRANSPORTER SECTION

- Item 17: **TRANSPORTER 1 ACKNOWLEDGEMENT**—Print or type the name of the person accepting the waste on behalf of the first transporter. That person must acknowledge acceptance of the waste described on the manifest by signing and entering the date of receipt.

- Item 18: **TRANSPORTER 2 ACKNOWLEDGEMENT**—If applicable, follow instructions for item 17 for the second transporter.

Note: ALL HAZARDOUS WASTE TRANSPORTERS OPERATING IN ARKANSAS MUST HAVE A VALID ARKANSAS TRANSPORTER PERMIT.

DESIGNATED FACILITY (TSDF) SECTION

- Item 19: **DISCREPANCY INDICATION SPACE**—The authorized representative of the designated facility must note in this space any significant discrepancy between the waste described on the manifest and the waste actually received at the facility. Any rejected materials should be listed here, along with an explanation of the disposition of the rejected wastes.

- Item 20: **FACILITY OWNER/OPERATOR CERTIFICATION**—Print or type the name of the person accepting the waste on behalf of the owner/operator of the designated TSDF. That person must acknowledge acceptance of the waste described on the manifest by signing and entering the date.

Note: For interstate shipments you may be required to comply with the manifesting requirements of both the receiving and generator states regarding the completion of specific information included in lettered items A-K. Please check with both generator and disposer states for specific requirements.

BURDEN DISCLOSURE STATEMENT

Public reporting burden for this collection of information is estimated to average: 37 minutes for generators, 15 minutes for transporters, and 10 minutes for treatment, storage and disposal facilities. This includes time for reviewing instructions, gathering data, and completing and reviewing the form. Send comments regarding the burden estimate, including suggestions for reducing this burden, to: Chief, Information Policy Branch, PM-223, U.S. Environmental Protection Agency, 401 M Street, S.W., Washington, D.C., 20460; and to the Office of Information and Regulatory Affairs, Office of Management and Budget, Washington, D.C., 20503.

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator's US EPA ID No. CAD086510005	Manifest Document No. 72048	22. Page 2 of 2	Information in the shaded areas is not required by Federal law.	
23. Generator's Name Douglas Aircraft Company			RBJ 03-24-93		L. State Manifest Document Number AR-572048	
24. Transporter <u>1</u> Company Name United Pumping Services			25. US EPA ID Number CAD072953771		M. State Generator's ID HAH036005698	
26. Transporter _____ Company Name			27. US EPA ID Number		N. State Transporter's ID PC1123 H602	
					O. Transporter's Phone 213-268-3137	
					P. State Transporter's ID	
					Q. Transporter's Phone	
28. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)			29. Containers	30. Total Quantity	31. Unit Wt/Vol	R. Waste No.
a. Waste Barium Nitrate (lab-pack) Oxidizer, UN1446			No. Type			551 D001
b. Waste Flammable Liquid, nos (lab-pack) Flammable Liquid, UN1993			No. Type			551 D001
c. Waste Poison B Liquid, nos (lab-pack) Poison B, UN2810			No. Type			551 P106, D005 D007, D006
d. Waste Titanium metal powder, dry (lab-pack) Flammable Solid, UN2546			No. Type			551 D001
e. Waste Organic Peroxide Liquid, nos (lab-pack) Organic Peroxide, NA9183			No. Type			551 D001
f. Waste Poison B solid, nos (lab-pack) PoisonB, UN2811			No. Type			551 D006
g. Waste Corrosive Liquid, nos (lab-pack) Corrosive Material, UN1760			No. Type			551 D002
h.						
i.						
S. Additional Descriptions for Materials Listed Above			T. Handling Codes for Wastes Listed Above			
a)drum# DT-005 e)drum# DT-009 all drums b)drum# DT-006 f)drum# DT-010 Profile# 200565 c)drum# DT-007 g)drum# DT-012,011 d)drum# DT-008						
32. Special Handling Instructions and Additional Information In case of an emergency contact Chemtrec at 800-424-9300. Weights are approximate. DOT# a)42 b)27 c)55 d)37 e)52 f)53 g)60						
33. Transporter _____ Acknowledgement of Receipt of Materials					Date	
Printed/Typed Name			Signature		Month Day Year	
34. Transporter _____ Acknowledgement of Receipt of Materials					Date	
Printed/Typed Name			Signature		Month Day Year	
35. Discrepancy Indication Space						

**CERTIFICATION**

P.O. BOX 8513 333 EXECUTIVE COURT LITTLE ROCK, AR 72205 (501) 223-4160

No. 112487

Invoice No. 106850

CERTIFICATE OF DISPOSAL

DOUGLAS AIRCRAFT CO.
ATTN: ROB TUELL
19503 S. NORMANDIE AVE.
M/S C6-10
TORRANCE, CA 90502

ENSCO CERTIFIES THAT THE ITEMS ASSOCIATED WITH THE SHIPMENT IDENTIFIED BY MANIFEST AR000572048 RECEIVED FROM DOUGLAS AIRCRAFT CO. HAVE BEEN PROCESSED AS DESCRIBED BELOW:

IDENTIFICATION NUMBER	DESCRIPTION	DISPOSAL DATES	DISPOSAL PROCESS/PROCESSES
1. AR000572048	001 NON RCRA HAZARDOUS WASTE	01/13/93 -- 01/13/93	INCINERATION
2. AR000572048	002 NON RCRA HAZARDOUS WASTE	01/13/93 -- 01/13/93	INCINERATION
3. AR000572048	003 WASTE SODIUM NITRATE	01/14/93 -- 01/14/93	INCINERATION
4. AR000572048	004 NASTEBARIUM NITRATE	01/14/93 -- 01/14/93	INCINERATION
5. AR000572048	005 WASTE FLAMMABLE LIQUID	01/14/93 -- 01/14/93	INCINERATION
6. AR000572048	006 WASTE POISON B LIQUID	01/14/93 -- 01/14/93	INCINERATION
7. AR000572048	007 WASTE TITANIUM METAL POWDER	01/13/93 -- 01/13/93	INCINERATION
8. AR000572048	008 WASTE ORGANIC PEROXIDE	01/14/93 -- 01/14/93	INCINERATION
9. AR000572048	009 WASTE POISON B SOLID	01/28/93 -- 01/28/93	INCINERATION
10. AR000572048	010 WASTE CORROSIVE LIQUID	01/13/93 -- 01/13/93	INCINERATION

BY _____

NAME _____

TITLE _____

DATE _____

ENSCO INCORPORATED

NOTICE

Enclosed is a Compliance Certificate, signed by an ENSCO employee, certifying proper disposal of your waste material.

Thank you for your confidence in ENSCO. We appreciate the opportunity to provide hazardous waste management services to your company.

When you need us, call your ENSCO representative or sales manager.



CERTIFICATION

P.O. BOX 8513 333 EXECUTIVE COURT LITTLE ROCK, AR 72205 (501) 223-4160

No.

00112487

CERTIFICATION ATTACHMENT 1

IDENTIFICATION
NUMBER

DESCRIPTION

DISPOSAL
DATES

DISPOSAL
PROCESS/PROCESSES

INCINERATION OCCURRED AT ENSCO, INC., AMERICAN OIL ROAD, ELDORADO, AR 71730 EPA ID NUMBER ARD069746192.

BY _____

NAME SHANE DANIEL

TITLE INVENTORY ACCOUNTING MANAGER

DATE 1/28/93

IF YOU HAVE ANY QUESTIONS, PLEASE CONTACT YOUR ENSCO SALES REPRESENTATIVE.
ENSCO INCORPORATED

NOTICE

Enclosed is a Compliance Certificate, signed by an ENSCO employee, certifying proper disposal of your waste material.

Thank you for your confidence in ENSCO. We appreciate the opportunity to provide hazardous waste management services to your company.

When you need us, call your ENSCO representative or sales manager.



STATE OF ARKANSAS
Department of Pollution Control and Ecology
P. O. Box 8913 Little Rock, Arkansas 72219-8913
Telephone 501-562-7444

6

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039. Expires 9-30-92

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No.		Manifest Document No.		2. Page 1 of 2		Information in the shaded areas is not required by Federal law.	
3. Generator's Name and Mailing Address Douglas Aircraft Co. Attn. R. Tuel M/S C6-59 19503 S. Normandie Ave. Torrance, CA 90502		6. Generator's Phone (310) 533-7926 or 310-533-7231		8. US EPA ID Number C A D 0 3 6 5 1 0 0 0 5 1		A. State Manifest Document Number AR-572048		B. State Generator's ID	
5. Transporter 1 Company Name United Pumping Services		7. Transporter 2 Company Name		8. US EPA ID Number C A D 0 7 2 0 5 3 7 7 1		C. State Transporter's ID PC 1123 H02		D. Transporter's Phone 213-268-3137	
9. Designated Facility Name and Site Address Ensco Inc. American Oil Rd. El Dorado, AR 71730		10. US EPA ID Number A R D 0 6 9 7 4 2 1 2 2		12. Containers		13. Total Quantity		14. Unit Wt/Vol	
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)		No.		Type		Total Quantity		Unit Wt/Vol	
a. Non-RCRA Hazardous Waste Solid (lab-pack)		101		D M		01/1810		P	
b. Non-RCRA Hazardous Waste Liquid (lab-pack)		101		D F		01/1810		P	
c. Waste Oxidizer, nos (lab-pack) Oxidizer, UN1479		101		D F		01/1810		P	
d. Waste Sodium Nitrate (lab-pack) Oxidizer, UN1498		101		D F		01/1810		P	
J. Additional Descriptions for Materials Listed Above a)drum# DT-001 c)drum# DT-003 all drums b)drum# DT-002 d)drum# DT-004 Profile# 200565		K. Handling Codes for Wastes Listed Above EMERGENCY RESPONSE INFORMATION: 310-533-7926 Rob Tuel		if no alternate TSDF, return to generator		15. Special Handling Instructions and Additional Information In case of emergency contact Chemtrec at 800-424-9300. Weights are approximate. DOT ERG# a)N/A b)N/A c)35 d)35		16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and Arkansas state regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.	
17. Transporter 1 Acknowledgement of Receipt of Materials		Printed/Typed Name John C. Tuel		Signature [Signature]		Month Day Year 11/17/91			
18. Transporter 2 Acknowledgement of Receipt of Materials		Printed/Typed Name Robert H. Tuel		Signature [Signature]		Month Day Year 11/17/91			
19. Discrepancy Indication Space									
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19.		Printed/Typed Name		Signature		Month Day Year			

EPA Form 8700-22 (Rev. 9-88) Previous edition is obsolete.

GENERATOR INITIAL COPY

BOE-C6-0194145

GENERATOR

501-863-7173



American Oil Road
P.O. Box 1957
El Dorado, Arkansas 71731

DATE:

01-08-93

Douglas Aircraft Co.
19503 S. Normandie Ave
Lorrance, Ca. 90502
Attn: R. Twell MS C6-59

Re: Arkansas Manifest #

572040

Dear Sir/Madame:

This letter is to notify you of an estimated weight discrepancy on the above referenced Arkansas manifest. The manifested estimate weight was RCRA 375 LBS. The actual weight as received by ENSCO's Receiving Department was RCRA 300 LBS.

Please retain this notification for your files. No further action on your part is necessary. If you have any questions, please feel free to call me at (501) 864-3608.

Sincerely,

Deleza E. Johnson
Data Center Manager

cc: File



STATE OF ARKANSAS
Department of Pollution Control and Ecology
P. O. Box 8913 Little Rock, Arkansas 72219-8913
Telephone 501-562-7444

1

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039. Expires 9-30-92

UNIFORM HAZARDOUS WASTE MANIFEST		1. Generator's US EPA ID No. C I A I D I O I B I 6 I 5 I 1 I 0 I 0 I 0 I 5 I		Manifest Document No.		2. Page 1 of 2		Information in the shaded areas is not required by Federal law.							
3. Generator's Name and Mailing Address Douglas Aircraft Co. Attn. R. Tuel M/S C6-59 19503 S. Normandie Ave. Torrance, CA 90502						A. State Manifest Document Number AR-572048									
4. Generator's Phone (310) 533-7926 or 310-533-7231						B. State Generator's ID									
5. Transporter 1 Company Name United Pumping Services						6. US EPA ID Number C I A I D I O I 7 I 2 I 9 I 5 I 3 I 7 I 7 I 1		C. State Transporter's ID PC 1123 602							
7. Transporter 2 Company Name						8. US EPA ID Number		D. Transporter's Phone 213-268-3137							
9. Designated Facility Name and Site Address Ensco Inc. American Oil Rd. El Dorado, AR 71730						10. US EPA ID Number I A I R I D I O I 6 I 9 I 7 I 4 I 8 I 1 I 9 I 2		E. State Transporter's ID PC - - - - H - - -							
								F. Transporter's Phone							
								G. State Facility's ID							
								H. Facility's Phone 501-863-7173							
11. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)						12. Containers No. Type		13. Total Quantity		14. Unit Wt/Vol		15. Waste No.			
a. Non-RCRA Hazardous Waste Solid (lab-pack)						I I D M		I I I I				551 N/R			
b. Non-RCRA Hazardous Waste Liquid (lab-pack)						I I D I F		I I I I				551 N/R			
c. Waste Oxidizer, nos (lab-pack) Oxidizer, UN1479						I I D I F		I I I I				551 D001			
d. Waste Sodium Nitrate (lab-pack) Oxidizer, UN1498						I I D I F		I I I I				551 D001			
J. Additional Descriptions for Materials Listed Above a)drum# DT-001 c)drum# DT-003 all drums b)drum# DT-002 d)drum# DT-004 Profile# 200565						K. Handling Codes for Wastes Listed Above EMERGENCY RESPONSE INFORMATION: 310-533-7926 Rob Tuel									
if no alternate TSDF, return to generator															
15. Special Handling Instructions and Additional Information In case of emergency contact Chemtrec at 800-424-9300. Weights are approximate. DOT ERG# a)N/A b)N/A c)35 d)35															
16. GENERATOR'S CERTIFICATION: I hereby declare that the contents of this consignment are fully and accurately described above by proper shipping name and are classified, packed, marked, and labeled, and are in all respects in proper condition for transport by highway according to applicable international and national government regulations and Arkansas state regulations. If I am a large quantity generator, I certify that I have a program in place to reduce the volume and toxicity of waste generated to the degree I have determined to be economically practicable and that I have selected the practicable method of treatment, storage, or disposal currently available to me which minimizes the present and future threat to human health and the environment; OR, if I am a small quantity generator, I have made a good faith effort to minimize my waste generation and select the best waste management method that is available to me and that I can afford.															
Printed/Typed Name JOHN CHAN						Signature <i>John Chan</i>						Month Day Year 12/1/98			
17. Transporter 1 Acknowledgement of Receipt of Materials Printed/Typed Name						Signature						Month Day Year			
18. Transporter 2 Acknowledgement of Receipt of Materials Printed/Typed Name						Signature						Month Day Year			
19. Discrepancy Indication Space															
20. Facility Owner or Operator: Certification of receipt of hazardous materials covered by this manifest except as noted in Item 19. Printed/Typed Name												Signature		Month Day Year	

Please print or type. (Form designed for use on elite (12-pitch) typewriter.)

Form Approved. OMB No. 2050-0039. Expires 9-30-91

UNIFORM HAZARDOUS WASTE MANIFEST (Continuation Sheet)		21. Generator's US EPA ID No. CAD086510005		Manifest Document No.		22. Page 2 of 2		Information in the shaded areas is not required by Federal law.	
		23. Generator's Name Douglas Aircraft Company		L. State Manifest Document Number AR-572048		M. State Generator's ID HAH036005698			
24. Transporter <u>1</u> Company Name United Pumping Services		25. US EPA ID Number CAD072953771		N. State Transporter's ID PC1123 H602		O. Transporter's Phone 213-268-3137			
26. Transporter _____ Company Name		27. US EPA ID Number		P. State Transporter's ID		Q. Transporter's Phone			
28. US DOT Description (Including Proper Shipping Name, Hazard Class, and ID Number)				29. Containers		30. Total Quantity		31. Unit Wt/Vol	
				No. Type					
GENERATOR	a.	Waste Barium Nitrate (lab-pack) Oxidizer, UN1446			D F			551 D001	
	b.	Waste Flammable Liquid, nos (lab-pack) Flammable Liquid, UN1993			D F			551 D001	
	c.	Waste Poison B Liquid, nos (lab-pack) Poison B, UN2810			D F			551 P106, D005 D007, D006	
	d.	Waste Titanium metal powder, dry (lab-pack) Flammable Solid, UN2546			D F			551 D001	
	e.	Waste Organic Peroxide Liquid, nos (lab-pack) Organic Peroxide, NA9183			D F			551 D001	
	f.	Waste Poison B solid, nos (lab-pack) PoisonB, UN2811			D F			551 D006	
	g.	Waste Corrosive Liquid, nos (lab-pack) Corrosive Material, UN1760			D F			551 D002	
	h.								
	i.								
S. Additional Descriptions for Materials Listed Above						T. Handling Codes for Wastes Listed Above			
a)drum# DT-005 e)drum# DT-009 all drums b)drum# DT-006 f)drum# DT-010 Profile# 200565 c)drum# DT-007 g)drum# DT-012,011 d)drum# DT-008									
32. Special Handling Instructions and Additional Information In case of an emergency contact Chemtrec at 800-424-9300. Weights are approximate. DOT# a)42 b)27 c)55 d)37 e)52 f)53 g)60									
33. Transporter _____ Acknowledgement of Receipt of Materials								Date	
Printed/Typed Name				Signature				Month Day Year	
34. Transporter _____ Acknowledgement of Receipt of Materials								Date	
Printed/Typed Name				Signature				Month Day Year	
35. Discrepancy Indication Space									



LAND DISPOSAL RESTRICTION NOTIFICATION FORM

SECTION I

Generator Name: Douglas Aircraft Co.

Manifest No.: AR-572048

SECTION II SPENT SOLVENT WASTE (268.30) AND CALIFORNIA LIST WASTE (268.32)

A. Spent Solvent Wastes (F001-F005)

This shipment, as referenced by the above manifest number, contains waste(s) which correspond to USEPA Hazardous Waste Code(s) _____

The above referenced waste(s) must be treated to meet the treatment standard expressed as Constituent Concentration in the Waste Extract as outlined in 40 CFR 268.41 Table CCWE or in 40 CFR 268.43 Table CCW below.

Table CCW – Constituent Concentrations in Waste

F001-F005 Spent Solvents	Total Concentration(in mg/l)	
	Wastewaters	Non-Wastewaters
Acetone	0.28	180
Benzene	0.070	3.7
n-Butyl alcohol	5.8	2.8
Carbon tetrachloride	0.057	5.8
Chlorobenzene	0.057	5.7
Cresols (m- and p- isomers)	0.77	3.2
O-cresol	0.11	5.8
O-Dichlorobenzene	0.088	6.2
Ethyl acetate	0.34	33
Ethyl benzene	0.057	8.0
Ethyl ether	0.12	180
Isobutyl alcohol	5.8	170
Methylene chloride	0.088	33
Methyl ethyl ketone	0.28	36
Methyl isobutyl ketone	0.014	33
Nitrobenzene	0.068	14
Pyridine	0.14	0.16
Tetrachloroethylene	0.058	5.8
Toluene	0.08	28
1,1,1-Trichloroethane	0.054	5.8
1,1,2-Trichloroethane	0.030	7.8
1,1,2-Trichloro-1,2,2-Trifluoroethane	0.057	0.28
Trichloroethylene	0.054	5.8
Trichlorofluoromethane	0.02	33
Xylenes (Total)	0.32	28

Table CCWE-Constituent Concentrations in Waste Extract

	TCUP Concentrations (mg/l)	
Carbon Disulfide	N/A	4.8
Cyclohexanone	N/A	.75
Methanol	N/A	.75

F005 Spent solvents 2-Nitropropane and 2-Ethoxyethanol have treatment standards outlined in 40 CFR 268.42 and must be referenced in Section III of this form.

☐ - If indicated by "X", any or all of the above specified waste codes are able to be land disposed without further treatment and are referenced to Certification Statement Section V.

"X" Here,
if applicable

B. California List Wastes

This shipment, as referenced by the above manifest number, contains waste(s) corresponding to USEPA Hazardous Waste Code(s) _____

The above referenced waste(s) must be treated to meet the treatment standards as set forth in 40 CFR 268 Subpart D, or where specific treatment standards are not applicable, or where the hazardous waste contains any of the constituents below not already covered under existing treatment standards, the waste must be treated in accordance with the requirements specified in 40 CFR 268.32 and RCRA Section 3004(d).

CALIFORNIA LIST CONSTITUENTS AND THEIR PROHIBITION LEVELS

CONSTITUENT	CONCENTRATION (MG/L)
*Cyanides	1,000
*Arsenic	500
*Cadmium	100
*Chromium VI	500
*Lead	500
*Mercury	20
Liquid Hazardous Waste Containing Nickel	134
*Selenium	100
Liquid Hazardous Waste Containing Thallium	130
*Liquids with pH ≤ 2.0	—
Liquids with PCBs	50 ppm
Hazardous Wastes containing HOCs**	1,000 mg/kg

*Generally, liquid hazardous wastes containing any of these constituents are subject to more specific treatment standards which supercede the California List Prohibitions and should be referenced in Section III of this form. However, some solid hazardous debris may be subject to an extension in the effective date and may be subject to these prohibitions if any of these constituents are contained in concentrations equal to or greater than what is specified.

**Halogenated Organic Carbon (See 40 CFR 268 Appendix III).

☐ - If indicated by "X", any or all of the above specified waste codes are able to be land disposed without further treatment and are referenced to certification statement Section V. "X" here, if applicable

SECTION III

OTHER RESTRICTED WASTES

Restricted Waste(s) contained in this shipment and referenced by the above manifest number are listed below and are subject to the treatment standards set forth in 268.41, 268.42, and/or 268.43.

For each waste code, list the following information where applicable: Subcategory; Treatability Group (NWW or WW); 5-letter treatment code for specified technology in 268.42 (INCIN, DEACT, STABL, RMERC, FSUBS) or CFR Section and Paragraph for concentration based standards [268.41(a) and/or 268.43(a)].

USEPA Hazardous Waste Code(s)	Subcategory If Applicable*	Treatability Group	Treatment Technology** (5-letter Treatment Code)	OR	CFR Section and Paragraph (268.41(a) and/or 268.43(a))	Waste Codes Indicated By "X" are Referenced to Certification Statement Section V
_____	_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____	_____

*Required for the following waste codes: D001, D002, D003, D006, D008, D009, F025, K069, K071, K106, P065, P092 and U151.

**Not all treatment codes are acceptable at the El Dorado, Arkansas facility. The three most common codes accepted are INCIN, DEACT, STABL.

SECTION IV**LAB PACK CERTIFICATION**

In accordance with 40 CFR 268.7(a)(8) and 268.7(a)(9), the lab pack wastes contained in this shipment corresponding to the USEPA Hazardous Waste Codes listed below

<u>D001</u>	<u>P106</u>	<u>D005</u>	<u>D007</u>	<u>D006</u>	<u>D002</u>	_____	_____
_____	_____	_____	_____	_____	_____	_____	_____
_____	_____	_____	_____	_____	_____	_____	_____

are identified as restricted wastes and are referenced by the above manifest number. I submit the following certification statement(s) where applicable:

**Appendix IV Lab Pack Wastes
(Organometallic)**

I certify under penalty of law that I personally have examined and am familiar with the waste and that the lab pack contains only the wastes specified in appendix IV to part 268 or solid wastes not subject to regulation under 40 CFR Part 261. I am aware that there are significant penalties for submitting a false certification, including the possibility of fine or imprisonment.

+ Signature _____

Title _____ Date _____

Treatment Technology: INCIN followed by STABL

Lab pack wastes with hazardous waste codes not specified by EPA in 40 CFR 268 Appendix IV or V are referenced in Section III of this form.

**Appendix V Lab Pack Wastes
(Organic)**

I certify under penalty of law that I personally have examined and am familiar with the waste through analysis and testing or through knowledge of the waste and that the lab pack contains only organic wastes specified in Appendix V to Part 268 or solid wastes not subject to regulation under 40 CFR Part 261. I am aware that there are significant penalties for submitting a false certification, including the possibility of fine or imprisonment.

Signature _____

Title _____ Date _____

Treatment Technology: INCIN

**SECTION V CERTIFICATION OF RESTRICTED WASTE WHICH MAY BE LAND DISPOSED
WITHOUT FURTHER TREATMENT**

In accordance with 268.7(a)(2) and regarding those restricted waste(s) contained in this shipment, these waste(s) may be land disposed without further treatment. I submit the following certification statement:

I certify under penalty of law that I personally have examined and am familiar with the waste through analysis and testing or through knowledge of the waste to support this certification that the waste complies with the treatment standards specified in 40 CFR Part 268 Subpart D and all applicable prohibitions set forth in 40 CFR 268.32 or RCRA section 3004(d). I believe that the information I submitted is true, accurate and complete. I am aware that there are significant penalties for submitting a false certification, including the possibility of a fine and imprisonment.

Signature _____ Title _____ Date _____

(This certification is referenced to the appropriate USEPA Hazardous Waste Code in the foregoing appropriate Sections II or III).

SECTION VI HAZARDOUS DEBRIS SUBJECT TO ALTERNATIVE TREATMENT STANDARDS

This shipment contains hazardous debris as defined in 40 CFR 268.2(h) and corresponding to USEPA waste codes

Effective November 9, 1992, this hazardous debris is subject to the alternative treatment standards of 40 CFR 268.45. This debris contains the following constituents subject to treatment:

- ☐ Constituents of treatment standards for the above listed wastes as described in 268.41 and/or 268.43.
- ☐ Toxicity Characteristics (D004-D043) _____
(Specify Chemical Name(s)) _____
- ☐ Reactive Sulfide or Cyanide

SECTION VII WASTES SUBJECT TO AN EXTENSION IN THE EFFECTIVE DATE
(Check Where Appropriate)

	<u>Waste Code</u>	<u>Effective Date</u>
<input type="checkbox"/>	F037	6-30-93
<input type="checkbox"/>	F038	6-30-93
<input type="checkbox"/>	F037 Debris	6-30-94
<input type="checkbox"/>	F038 Debris	6-30-94
<input type="checkbox"/>	Debris contaminated with a newly listed waste (specify code(s))	6-30-94

These wastes do not need to be referenced in Section III of this form. However, these wastes may be subject to the California List Prohibitions - See Section IIB of this form

Waste analysis is attached where available, otherwise, the information contained herein is based upon my thorough knowledge of the waste(s).

I hereby certify that all information submitted in this document is complete and accurate to the best of my knowledge and information.

* Signature [Signature] Title B. Tech Sp. Date 01/04/93 Rev. DA 10/92